


Laundry Symbols



Machine Wash



Machine Wash
Permanent Press



Machine Wash Gentle



Hand Wash




Do Not Wash




OK To Bleach



Do Not Bleach




Drip Dry




Lay Flat To Dry



Hang To Dry




Tumble Dry




Tumble Dry Low Heat




Tumble Dry High Heat



No Heat Tumble Dry



Do Not Tumble Dry



Dry Clean



Do Not Dry Clean



Do Not Wring



Short Cycle



No Steam Finishing



Iron Max Temp 230°F



Iron Max Temp 300°F



Iron Max Temp 390°F



Do Not Iron



Do Not Steam